INTERNATIONAL MARITIME ORGANIZATION
4 ALBERT EMBANKMENT
LONDON SE1 7SR

Telephone: 0171-735 7611
Fax: 0171-587 3210
Telex: 23588 IMOLDN G

IMO

E

Ref. T4/4.03

MSC/Circ.847/Corr.1
16 August 1999

INTERPRETATIONS OF VAGUE EXPRESSIONS AND OTHER VAGUE WORDING IN SOLAS CHAPTER II-2

Corrigenda

The following modifications are made to the interpretations contained in the annex to document MSC/Circ.847:

1 In regulation 18.1.1, interpretation 2, the word "interpretations" is replaced by "interpretation 2".

2 In regulation 27.2, the word "interpretation 2" is replaced by "interpretations".

3 In regulation 29.2, interpretation 1, the word "interpretations" is replaced by "interpretation 1".

4 In regulation 32.1.9.2, interpretation 1, the word "interpretations" is replaced by "interpretation".

5 In regulation 32.1.9.5, interpretation 1, the sentence "(See also interpretations of regulation II-2/41-2.4.3.5)"is added at the end of the interpretation.

6 In regulation 33.2, the existing text of the interpretation is replaced by the following:

"33.2 Reference is made to the following ISO standards:

ISO 614:1989	Shipbuilding and marine structures - Toughened safety glass panes for rectangular windows and side scuttles - Punch method of non-destructive strength testing
ISO 1095:1989	Shipbuilding and marine structures - Toughened safety glass panes for side scuttles
ISO 1751:1993	Shipbuilding and marine structures - Ships' side scuttles
ISO 3254:1989	Shipbuilding and marine structures - Toughened safety glass panes for rectangular windows
ISO 3903:1993	Shipbuilding and marine structures - Ships' ordinary rectangular windows
ISO 3904:1990	Shipbuilding and marine structures - Clear-view screens"

7 In regulation 34.1, interpretation 2, the word “interpretations” is replaced by “interpretation 1”.

8 In regulation 34.6, interpretation 1, the word “interpretations” is replaced by “interpretation 1”.

9 In regulation 34.6, interpretation 2, the word “interpretations” is replaced by “interpretation 2”.

10 In regulation 37.1.5.3, interpretation 1, the sentence “(See also interpretations of regulation II-2/38.2.3)” is added at the end of the interpretation.

11 In regulation 37.1.6.3, the word “interpretations” is replaced by “interpretation”.

12 In regulation 37.1.6.4, the word “interpretations” is replaced by “interpretation”.

13 In regulation 37.3.2.2, interpretation 1, the sentence “(See also interpretations of regulations II-2/37.2.2.2 and 38.4.2)” is added at the end of the interpretation.

14 In regulation 38.3.3, the word “interpretations” is replaced by “interpretation”.

15 In regulation 38.3.4, the word “interpretations” is replaced by “interpretation”.

16 In regulation 38.4.1, the word “interpretations” is replaced by “interpretation”.

17 In regulation II-2/41-2.4.5, the existing heading is replaced by “Escape stairway from machinery spaces”.

18 In regulation II-2/41-2.4.5, the sentence “(See also interpretation 2 of regulation II-2/29.2)” is deleted.

19 In regulation II-2/44.2, the words “interpretation to” are replaced by “interpretation 2 of”.

20 In regulation II-2/44.2, the number “27.2” is deleted.

21 In regulation 45.3.1, interpretation 1, the sentence “One of the means of escape required by regulation II-2/45.3.1 should be arranged as follows:” is replaced by “If a shelter is provided, it should be arranged as follows:”.

22 In regulation 54.2.5, interpretation 3, the second sentence is replaced by the following:

> “Electrical equipment in the space should comply with the International Standard IEC Publication 92-506: Electrical installations in ships - Part 506: Special features - Ships carrying specific dangerous goods and materials hazardous only in bulk.”.

23 In table 58.2, note e, the words “the interpretation of” are deleted.

_____